



Pos.	Part Number	Description {Qty.}	F/C	Pos.	Part Number	Description {Qty.}	F/C
1	2 605 104 681	Housing Assembly	71	49	2 605 133 018	Handle Cover	74
2	2 604 220 644	Field 115V	22	50	2 608 584 003	Cutter Drum Assembly w/pos. 751,852,853,855,856	48
3	2 604 011 214	Armature w/Fan 115V w/pos. 813	AW	54	1 907 950 003	Allen Wrench	9
4	2 607 200 534	Switch On/Off	15	60	2 600 409 025	Air Deflector Tube	9
6	2 600 703 018	Strain Relief	11	751	PA1202	Blade	94
9	2 610 998 874	Label "Bosch"	9	+ 781	2 607 000 073	Rabbeting Depth Stop	9
14	1 610 905 011	Ball Bearing	61	782	PA1203	Parallel Fence	9
16	2 604 337 087	Brush Holder Assembly w/pos. 816/4	25	782/2	1 603 339 006	Knob	63
19	2 914 201 705	Screw {18}	89	782/3	2 916 011 004	Washer	65
25	2 604 736 001	Drive Belt	50	782/4	2 910 281 197	Bolt	89
26	2 603 100 056	Rubber Pin {4}	9	782/5	1 601 332 018	Bracket	9
27	2 608 000 243	Base	72	782/6	2 603 480 006	Wing Screw	89
30	2 605 500 157	Housing Cover	70	782/7	1 610 210 043	O-Ring	78
33	2 608 000 224	Front Shoe	88	+ 786	2 605 411 035	Chip Bag	9
34	2 608 000 225	Base Plate	88	+ 788	2 605 702 022	Vacuum Connector	9
35	1 610 910 057	Needle Bearing	56	805	3 604 460 555	Cord	11
36	2 601 329 074	Tool Rest	9	808	2 610 998 442	Nameplate	9
37	2 602 026 094	Handle	74	813	2 600 905 051	Ball Bearing	60
41	2 915 011 007	Nut {3}	89	816/4	2 604 321 914	Brush Set	26
42	2 606 625 030	Drive Pulley	36	852	2 603 111 001	Blade Holder	9
44	2 604 448 221	Cable 300mm	10	853	2 603 400 016	Set Screw {2}	89
45	2 604 448 222	Cable 325mm	10	855	3 600 900 514	Ball Bearing	51
47	2 600 590 006	Cap / Spring {2}	9	856	2 606 625 031	Driven Pulley	36

+ = Not Illustrated * = As Required F/C = Failure Code AW = Refer to AW Labor Time Chart