



CODE-TO-FIX IN 40 SECONDS

tÜ

NOW WITH HEAVY-DUTY SOFTWARE & WIRELESS TPR*

0

The first integrated diagnostics tablet for Android[™] with fast startup and onboard battery has just released wireless TPR and Heavy-Duty software.* Pair up with the optional 3834T OTC TPR TPMS Tool via Bluetooth[®]. The new 3895-07 Heavy-Duty Standard kit is available for reading DTCs and viewing live data on Class 4 – 8 vehicles.

No tool helps you fix faster than OTC Encore 00:00:15 Boot up in less than 15 seconds 00:00:05 AutolD faster than

anybody — identify CAN vehicles in less than 5 seconds 00:00:02 Read and clear codes in seconds 00:00:00 Access top reported code fixes in seconds

Check out the Encore TPMS registration process here.

encore

•11•



AVAILABLE OCTOBER 2014

Battery Disconnect Procedures, Key FOB and Remote Reprogramming!

The battery update covers Domestic and Import vehicles 2000 to present, with partial coverage for 1991-1999. Procedures include battery disconnection precautions, power windows, locks and sunroof reprogramming, engine and body control system resetting and more.

The key and remote programming update covers Domestic and Import vehicles 1996 to present, with partial coverage for 1993-1995. Procedures include system operation, unusual features, programming procedures, illustrated battery replacement procedures for remote and key transmitters and more.

QUESTIONS?

800 533 6127





3895 GENISYS TOUCH™ ELECTRONIC DIAGNOSTICS

FASTEST DIAGNOSTIC FLOW IN THE INDUSTRY

ROAM THE SHOP FLOOR WITH WIRELESS J2534 COMPLIANT VCI



CONTINUING COVERAGE IMPROVEMENTS

Get the most of the 12-month subscription by updating your tool! The latest updates include:

- New USA Domestic / Asian / European vehicle coverage with multiple releases through the year!
- Frequent updates to the largest experienced based solutions available, already with over 30 million specific fixes!
- Performance improvements, user interface, repair information and product enhancements included!

AVAILABLE Q4 2014

Battery Disconnect Procedures, Key FOB and Remote Reprogramming!

The battery update covers Domestic and Import vehicles 2000 to present, with partial coverage for 1991-1999. Procedures include battery disconnection precautions, power windows, locks and sunroof reprogramming, engine and body control system resetting and more.

The key and remote programming update covers Domestic and Import vehicles 1996 to present, with partial coverage for 1993-1995. Procedures include system operation, unusual features, programming procedures, illustrated battery replacement procedures for remote and key transmitters and more.

> QUESTIONS? 2 800 533 6127



otctools.com/genisystouch